

MANUAL FORK OVER STACKER

WMS

Make
Your Job
Easier

www.staxxmhe.com



WMS

STAXX
STAXX MATERIAL HANDLING EQUIPMENT CO., LTD

MANUAL FORK OVER STACKER

MODEL				WMS500-1600				WMS1000				WMS1500				WMS2000-1600			
FEATURE																			
1.1	Capacity			Q	kg	500				1000				1500				2000	
1.2	Load Center			C	mm	600													
DIMENSIONS																			
2.1	Lifting height			h	mm	1600				1600	2000	2500	3000	1600	2000	2500	3000	1600	
2.2	Maslowered height			H	mm	1970				2020	1500	1770	2020	2070	1500	1770	2020	2110	
2.3	Masextend height			H1	mm	1970				2020	2510	3010	3510	2070	2510	3010	3510	2110	
2.4	Mast type					S				S	D	D	D	S	D	D	D	S	
2.5	Lowered height of fork			h1	mm	95				90				90				90	
2.6	Fixed fork outside distance			W	mm	560		680		560		680		560		680		560 680	
2.7	Option Ad justabke fork, adjsustable range				mm	230-870		230-680		230-870		230-680		230-870		230-680		230-870 230-680	
2.8	Fork length			sl	mm	1150				1150				1150				1150	
2.9	Overall width			W2	mm	780				780	870	870	870	780	870	870	870	780	
2.10	Overall length			L	mm	1650													
2.11	Lifting speed				mm/time	≥16													
2.12	Lowering speed					Controllable													
2.13	Turing Radius			Wr	mm	1590				1590	1600	1600	1600	1590	1600	1600	1600	1590	
WHEEL																			
3.1	wheel(drive/load) Type					PU/Nylon				PU/Nylon				PU/Nylon				PU/Nylon	
3.2	size of steering wheel			∅D	mm	∅ 180*50				∅ 180*50				∅ 180*50				∅ 180*50	
3.3	size of Loading wheel			∅d	mm	∅ 80*60				∅ 80*60				∅ 80*60				∅ 80*60	

www.staxxmhe.com

